

# GENSETS AT HICKMANS

LOCATION	Tonopah	UNIT #	TB-2	GENSET# 30	east genset between 1 & 2		
	laybarn						
ENG. INFO				GEN INFO			
SER #	73679699		HP RATE	SER. #	E140681677		
MOD. #	QSL9-G7		GALS.	MOD. #	DQDAA-A049N664		
S.O. #				VOLTS	480		
REF. #				AMPS	375		
FILTER INFO							
AIR	OIL	FUEL	WATER	LAST OIL SERVICE	5/19/16		
9708	1748XD	3697	n/a	HOURS	86		
		3732		CURRENT HOURS AS OF	86	5/19/16	
BATTERY INFO		2-4D	LAST BATTERY SWAP OUT				
ENG. OIL CAP.	8 gals plus 1 gal lucas						
COOLANT CAP.							

[illegible]

## GENSET REPAIRS # 30

DATE	HOURS	REPAIRS MADE
1/28/16 -6119	73.9	starter solinoid failed, we replaced with our's until Cummins could come to site for warranty repairs. Repairs made by Cummins on 2/5/16 WO# 274781